






















Part list

- A** X2 
- B** X1 
- C** X1 
- D** X1 
- E** X2 
- F** X2 
- G** X4 
M10x60MM
- H** X1 
M10
- I** X1 
M10
- J** X2 
- K** X2 
- L** X2 
- M** X2 
M6
- N** X2 
M6x15MM
- O** X1 
M4
- P** X2 
M6
- Q** X2 
- R** X2 
- S** X8 


Step 1



Step 2



Step 4



Step 3

